



## Markslöjd AB Gränevägen 5 S-511 62 Skene Sweden





106214 \, 106215 ARES www.markslojd.com



















- 1. Its standard set including 3pcs spots only, but it can be use 3-6pcs spots as a system.
- 2. If use less than opcs spots then the empty ports of the junction box should be insert with circuit breaker.

